

ISO TAPERS

ISO TAPERS

ISO Tapers						
QC30 & QC40 shanks have flanges to suit B.E. Quick Change spindles						
Taper	A	G	L	L1	L2	T
QC30	46.0	31.75	68.33	8.74	1.96	M12
QC40	63.5	44.45	93.73	7.95	1.93	M16
IT401	64.0	44.45	93.73	8.15	1.83	5/8" UNC
DT50	97.2	69.85	126.8	12.0	3.2	M24

